Global Parts Order Processing Material Safety Data Sheet SELKIRK CHRYSLER (MB) LTD.

CHRYSLER

HAZARD COMMUNICATION SHEET 291746 DRAFT PART/COMMTY CD: 0VU01348 EFFECTIVE DATE: 02/17/11 SUPPLIER: 86056 MFGR: 03500 STANDARD: N/AV *** SECTION 01 - PRODUCT INFORMATION *** MFG BY: PART SALES & SERVICE CHRYSLER 26311 LAWRENCE AVE CENTERLINE MI EMERGENCY PHONE: 248-512-8002 AFTER HOURS: 248-576-8888 CHRYSLER DIST BY: PART SALES & SERVICE 26311 LAWRENCE AVE CENTERLINE MI 48015 EMERGENCY PHONE: 248-512-8002 AFTER HOURS: 248-576-8888 CHRYSLER INDUSTRIAL HYGIENE: 248-512-8260 AFTER HOURS: 248-576-8888 BRAND NAME: MOPAR BATTERY CLEANER, 210G : BATTERY CLEANER 210G DESCRIPTION: CLEANER-BODY, TRIM, GLASS PRODUCT IDENTIFICATION NUMBER (PIN): UN1950 *** SECTION 02 - INGREDIENTS *** HAZARDOUS INGREDIENTS: PERCENT CHRYSLER COMM NAME / CAS NO & CHEM NAME: BY WGT TWA STEL CEIL UNITS NOTATIONS ***EXISTING INGREDIENTS*** AMMONTA 1-5 25 35 N/AP PPM 007664-41-7 AMMONIA (8CI9CI) LD50: 350.000MG/KG ORL RAT IDLH: 300 PPM LC50: 2000.000PPM IHL RAT PETROLEUM GASES, LIQUEFIED, SWEET 1-5 1000 N/AP N/AP PPM 068476-86-8 PETROLEUM GASES, LIQUE LD50: N/AV N/AV N/A N/A IDLH: 9000 PPM LC50: N/AV N/AV N/A N/A SODIUM PHOSPHATE (NA3PO4) 1-5 N/AP N/AP N/AP 007601-54-9 PHOSPHORIC ACID, TRISO LD50: > 20.000MG/KG SKN RBT IDLH: N/AP LC50: N/AV N/AV N/A N/A GENERIC DESC: N/AV FOR EXPLANATION OF "NOTATIONS", SEE THE HAZARD COMMUNICATION SHEET EXPLANATIONS PAGE. CONSULT LOCAL AUTHORITIES FOR ACCEPTABLE EXPOSURE LIMITS. *** SECTION 03 - PHYSICAL DATA *** BOILING POINT : N/AV SOLUB IN WATER: N/AV VAPOR PRESSURE: N/AV EVAP. RATE: N/AV REF: N/AV VAPOR DENSITY : N/AV SPECIFIC GRAVITY: N/AV PH AT FULL STRENGTH: N/AV PH AT REC. DILUT:

Page 1 of 3

ODOR THRESHOLD: N/AV PPM FOR % POPULATION

VOLATILE ORGANIC COMP: N/AV N/AV

%VOLATILE BY VOL : N/AV

| FREEZING POINT: N/AV COEFF. OF WATER/OIL DIST: N/AV APPEARANCE & ODOR: COMMENT MISSING FOR THIS PART, TO BE ADDED IN FUTURE. |
|--|
| *** SECTION 04 - FIRE AND EXPLOSION DATA *** |
| FLASH POINT: N/AV N/AV IGN TEMP: N/AV LEL: N/AV UEL: N/AV SPECIAL FIRE & EXPLOSION HAZARDS: |
| COMMENT MISSING FOR THIS PART, WILL BE ADDED IN FUTURE. EXTINGUISHING MEDIA: COMMENT MISSING FOR THIS PART, WILL BE ADDED IN FUTURE. |
| SPECIAL FIREFIGHTING PROCEDURES: COMMENT MISSING FOR THIS PART, WILL BE ADDED IN FUTURE. |
| FLAMMABILITY CONDITIONS: COMMENT MISSING FOR THIS PART, WILL BE ADDED IN FUTURE. |
| SENSITIVE TO MECHANICAL IMPACT?: N/AV SENSITIVE TO STATIC DISCHARGE?: N/AV HAZARDOUS COMBUSTION PRODUCTS: |
| FLAME PROJECTION: N/AP FLAMMABILITY: NO |
| *** SECTION 05 - REACTIVITY DATA *** |
| STABILITY: N/AV CONDITIONS TO AVOID: COMMENT MISSING FOR THIS PART, TO BE ADDED IN FUTURE. |
| MATERIALS TO AVOID: COMMENT MISSING FOR THIS PART, TO BE ADDED IN FUTURE. |
| POLYMERIZATION CONDITIONS TO AVOID: COMMENT MISSING FOR THIS PART, TO BE ADDED IN FUTURE. HAZARDOUS DECOMPOSITION PRODUCTS: |
| N/AV |
| *** SECTION 06 - TOXICOLOGICAL PROPERTIES *** |
| EFFECTS OF OVEREXPOSURE-ACUTE & CHRONIC: <pre></pre> |
| TOXICOLOGICALLY SYNERGISTIC PRODUCTS: PRODUCT LD50: N/AV N/AV N/AV |
| PRODUCT LD50: N/AV N/AV N/AV N/AV N/AV PRODUCT LC50: N/AV N/AV N/AV N/AV |

C6522000 S42090M

Global Parts Order Processing Material Safety Data Sheet SELKIRK CHRYSLER (MB) LTD.

March 14, 2013 14:55

*** SECTION 07 - PREVENTIVE MEASURES *** RESPIRATORY PROTECTION: N/AV VENTILATION TYPE: N/AV PROTECTIVE GLOVES: N/AV EYE PROTECTION: N/AV OTHER PROTECTIVE EQUIP: N/AV STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED: N/AV WASTE DISPOSAL METHODS: PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE: N/AV OTHER PRECAUTIONARY MEASURES: N/AV ______ *** SECTION 08 - FIRST AID MEASURES *** EMERGENCY FIRST AID PROCEDURES: <---INHALATION--->> REMOVE TO FRESH AIR AT ONCE. IF PULMONARY SYMPTOMS DEVELOP, CONSULT A PHYSICIAN. IF BREATHING IS DIFFICULT, GIVE OXYGEN. ARTIFICIAL RESPIRATION IF BREATHING HAS STOPPED. CARDIAC RESUSCITATION IF

DEVELOP, CONSULT A PHYSICIAN. IF BREATHING IS DIFFICULT, GIVE OXYGEN.

ARTIFICIAL RESPIRATION IF BREATHING HAS STOPPED. CARDIAC RESUSCITATION IF
INDICATED. <---SKIN CONTACT--->> REMOVE CONTAMINATED CLOTHING. WASH WITH
SOAP AND WATER. APPLY SKIN CREAM IF DEFATTING OF SKIN OCCURS. IF CONDITION
PERSISTS, CONSULT A PHYSICIAN. <---EYE CONTACT--->> REMOVE CONTACT LENSES
TO ASSURE COMPLETE FLUSHING. RINSE EYES IMMEDIATELY WITH LARGE AMOUNTS OF
WATER, OCCASIONALLY LIFTING BOTH UPPER AND LOWER LIDS. CONTINUE FOR 15
MINUTES. CONTACT A PHYSICIAN. <---INGESTION--->> GIVE SEVERAL GLASSES OF
WATER OR MILK TO DRINK. CONTACT A PHYSICIAN. NEVER GIVE ANYTHING BY MOUTH TO
AN UNCONSCIOUS PERSON. IF VOMITING OCCURS, KEEP HEAD BELOW HIPS TO PREVENT
LIQUID FROM SEEPING INTO THE WINDPIPE AND LUNGS.

*** SECTION 09 - PREPARED BY INFORMATION ***

DATA SHEET PREPARED BY:

CHRYSLER

INDUSTRIAL HYGIENE DEPARTMENT

TENE DEPARTMENT PREPARED BY:

REVIEWED BY:

PHONE: 248-512-8260

REVISED BY: